



Research paper

Settlement of a historic building due to seepage-induced soil deformation

Paweł Popielski¹, Bartosz Bednarz², Tomasz Majewski^{3,4},
Maciej Niedostatkiwicz⁵

Abstract: The research paper reviews issues associated with the impact of groundwater flow on soil characteristics and parameters, hence, the entire structure of a building set on it. Water seepage through the ground, building subsoil or structural elements of buildings made of soil affects the soil skeleton and may lead to changes in the arrangement of individual grains relative to each other, i.e., a modified soil structure. Soil solid phase (soil skeleton) deformations resulting from seepage forces are called seepage-induced deformations. The article characterizes typical seepage-induced deformations and specifies a criterion defining the beginning of the phenomenon. The case study involved using data on cracks and deformations in a historic building, as well as water seepage in its subsoil. Seepage was analysed, and zones where the seepage process initiation criterion was exceeded, were determined based on subsoil water level monitoring data. The determined zones coincide with the location of building cracks and scratches and confirm the possible cause behind building damage.

Keywords: building subsoil, seepage in the ground, settlement of building, seepage-induced deformation

¹DSc., PhD., Eng., Associate Professor, Warsaw University of Technology, Faculty of Building Services, Hydro and Environmental Engineering, Department of Hydro Engineering and Hydraulics, ul. Nowowiejska 20, 00-653 Warsaw, Poland, e-mail: pawel.popielski@pw.edu.pl, ORCID: 0000-0002-5425-5821

²MSc Eng., Warsaw University of Technology, Faculty of Building Services, Hydro and Environmental Engineering, Department of Hydro Engineering and Hydraulics, ul. Nowowiejska 20, 00-653 Warsaw, Poland, e-mail: bartosz.bednarz@pw.edu.pl, ORCID: 0000-0002-3791-5234

³MSc Eng., Gdańsk University of Technology, Doctoral School of Implementation, ul. Gabriela Narutowicza 11/12, 80-233 Gdańsk, Poland, e-mail: tomimaj@pg.edu.pl, ORCID: 0000-0003-0444-8753

⁴MSc Eng., Pracownia Projektowo-Inżynierska [Design and Engineering Studio] Tomasz Majewski, Os. Sierakowskich 9B lok. 3. 82-400 Sztum, Poland

⁵DSc., PhD., Eng., Associate Professor, Gdańsk University of Technology, Faculty of Civil and Environmental Engineering, Department of Concrete Structures, Gdańsk, Poland, e-mail: mniedost@pg.edu.pl, ORCID: 0000-0002-6451-6220

1. Introduction

Water seepage through the ground, building subsoil or structural elements of buildings made of soil affects the soil skeleton and may lead to changes in the arrangement of individual grains relative to each other, i.e., a modified soil structure [1–3]. Soil solid phase (soil skeleton) deformation resulting from seepage forces are called seepage-induced deformations. Such phenomena occur not only in hydrotechnical structures, but also in the subsoil of other buildings in cities and highly urbanized environments [4–6]. They also apply to the subsoil of historic buildings, where they usually significantly impact the condition of their structural elements [7].

An accurate technical assessment of building condition as a whole is an issue that requires professional experience [8–11], while the evaluation of the technical condition of historic buildings is one of the most difficult tasks in civil engineering [12–21]. This results directly from the specificity of such facilities, the execution of which involved often currently obsolete construction technologies and natural materials, such as stone, lime, clay, wood and reed.

The reconnaissance of the structural system of historic buildings, including religious, cannot be limited only to assessing the changing strength parameters of the materials themselves, and evaluating the structural systems that were used to erect such buildings [22–26], but must also involve the parameters of the subsoil the structure is set on. The assessment of changes in the subsoil parameters requires special consideration of the impact of numerous external factors on the changes of the water and soil conditions in the subsoil, which result from the particular location of the buildings. Changes in the development of urban space – urbanized areas, which involves the construction of infrastructural networks or road pavement compaction in the immediate and more distant vicinity of new buildings, often with a multi-storey underground section, entail changes in the hydrology of urbanized areas and groundwater levels [6]. Changes in the groundwater levels may lead to changed parameters of the structural elements used to execute the underground part of the building, as well as the geotechnical parameters of the subsoil the building is set on [7, 27, 28]. The number of factors affecting building and subsoil parameter changes make the reconnaissance and diagnostics of their technical condition an extremely difficult engineering tasks [29].

2. Soil seepage-induced deformation characteristics

When it comes to design studies related to historic buildings, civil engineers must work in teams consisting of specialists dealing with general construction, masonry, and wooden structures in particular, as well as geotechnical specialists.

The mechanical impact of seepage forces on the soil skeleton may lead to its deformations. Soil, solid phase deformations caused by the action of seepage forces are called seepage-induced deformations or local seepage strains [30]. Seepage-induced deformations usually cover small soil masses (grain, particle or lump displacements) and result in changes of soil condition and internal structure, hence, its parameters.

Seepage-induced deformations resulting from the displacement of individual soil grains and particles regardless of each other and under the influence of seepage forces can be called microdeformations. Such seepage-induced deformations are particularly frequent in non-cohesive soils.

Generally, the creation of seepage-induced deformations and their development are usually very complex and depend on numerous factors. Therefore pure-form seepage-induced deformations can be observed very rarely [29]. Seepage-induced deformations can have different causes, while the source literature often calls their causative factor as seepage-induced deformations, one terms applies to various processes or phenomena, or the same process or phenomenon is called differently [29]. Seepage-induced deformations are called different names. The most frequent ones include uplift [29], quicksand [29], hydraulic piping [27, 31], suffosion [29], erosion [29] and silting-up [27]. In addition, the latter three, owing to the nature of the phenomenon, are described using such adjectives as internal, external or contact. Fig. 1a shows a diagram of internal suffosion, Fig. 1b shows external suffosion, while Fig. 1c shows contact suffosion. Erosion is also divided into internal (Fig. 2a), external (Fig. 2b) and contact (Fig. 2c). Fig. 2d shows the most dangerous phenomenon – hydraulic piping [27]. The phenomena induced by the mechanical impact of water on the soil skeleton may lead to excessive settlement and, consequently, to a construction failure or even disaster [27].




Fig. 1. Types of suffosion: a) internal, b) external, c) contact [32]

The occurrence of a given deformation type will depend on [27]:

- nature of the phenomenon [29]: soil grain and particle displacement regardless of each other (microdeformations) or the displacement of a large volume of soil under the impact of seepage forces or uplift (macrodeformations),
- type of soil in terms of cohesion [27, 33, 34]: cohesive or non-cohesive,
- type of soil medium [27, 35]: homogeneous (built of a single soil type, the graining of which in various point of the volume is described by the same grain size curve, i.e., is characterized by the same granulometric composition) or layered (built of at least two different homogeneous soil layers, each of which has the same granulometric composition at various points within its volume, i.e. grain size curves are identical, with these soils being soils of different graining relative to each other, i.e., grain size curve characterizing these soils are different),




Fig. 2. Types of erosion: a) internal, b) external, c) contact, d) hydraulic piping [32]

- phenomenon location within the soil volume in question [27]: inside, on the surface, within a crevice in the soil medium or interbedding, in the contact zone between the soil and the concrete element of the building or in the contact zone between two soil layers,
- soil type in terms of varying granularity [27, 35]: sorted (built of particles and grains of the same size) and unsorted (built of grains and particles of different size),
- water flow direction relative to Earth's gravity [27]: vertical up, vertical down or horizontal,
- flow direction relative to layer surface [27]: perpendicular to the layer surface or parallel to the layer surface.

It should be noted that an unsorted soil is a suffusive soil, i.e., different grains and particles can be transported out of its volume under given seepage conditions. The concept of soil suffosiveness is relative, since it depends on load conditions and seepage gradients. The phenomenon of suffosion (suffusive soil) can occur under relatively low vertical loads on the soil and relatively high hydraulic gradients, and the phenomenon might not occur under relatively high loads and low hydraulic gradients, as is the case with a non-suffusive soil. An ideal non-suffusive soil is a sorted soil, built of particles (grains) with uniform sizes (graining uniformity coefficient $C_U = 1.0$).

The conditions for the occurrence of seepage-induced deformations are often described by a critical gradient or critical rate value, i.e., a hydraulic criterion (sufficient condition) relative to the soil volume unit, within which a given phenomenon is observed for a given gradient or rate [31, 38].

Water flow within a soil medium is induced by the difference in pressure between the initial point and the end point of the water molecule seepage path. Seepage direction is

consistent with seepage forces acting on the soil volume unit. Seepage forces generally tend to displace the soil towards flowing water along its entire considered volume, and the so-called run-off pressure j_v can be secluded.

Run-off pressure j_v , also called hydrodynamic pressure is the pressure applied on the soil skeleton and water, which balances the water-soil particle friction forces, relative to the soil volume unit. [30]

$$(2.1) \quad j_v = \gamma_w \cdot i$$

where: i – means the seepage pressure gradient, γ_w – means the water specific gravity.

The seepage pressure gradient is a ratio of pressure losses along the seepage section Δh_f and the seepage path length Δs .

$$(2.2) \quad i = \frac{\Delta h_f}{\Delta s}$$

According to [36], the gradients of seepage pressure occurring in the subsoil of all hydrotechnical structures and within the earth dam body should satisfy the relationship:

$$(2.3) \quad \gamma_i \cdot i \leq i_{kr}$$

where: i – means the seepage pressure gradient, i_{kr} – means the critical gradient values for a given soil, γ_i – means the confidence factor, which, irrespective of the building class, is:

$\gamma_i = 1.5$ for a basic load system,

$\gamma_i = 1.3$ for a unique load system.

The aforementioned assumptions can also be adopted equally for other buildings and structures set on a subsoil that experiences seepage pressure gradients.

The values i_{kr} can be determined using for example the Bligh method [37, 38] for the underground building or structure contour, by matching the C_B coefficient, which depends on the soil type and by determining the i_{kr} critical gradient as an inverse to the C_B coefficient:

$$(2.4) \quad i_{kr} = \frac{1}{C_B}$$

Coefficient values for all subsoil types are listed in Table 1.

Table 1. Bligh coefficients and critical seepage gradients, depending on the subsoil soil type [37]

Soil type	Bligh coefficient C_B [-]	i_{kr} [%]
Very fine sand, silts	18.0	5.5
Fine sand	15.0	6.6
Coarse sand	12.0	8.3
Fine-grain gravel	9.0	11.1
Medium-grain gravel	5.0	20.0

Exceeding the critical seepage pressure gradient for a given soil, which is the loss of soil seepage resistance may lead to seepage-induced deformations. This may especially occur in varied-grained soils, where finer particles and grains may be lifted and displaced according to the seepage direction, resulting in the change of the original soil skeleton density, thus leading to its deformation (settlement, uplift or piping).

3. Soil seepage-induced deformations within the area of the St. Nicholas basilica in Gdańsk – case study

3.1. Technical condition characteristics

Up until the autumn of 2018, the Basilica building was in a satisfactory technical condition, approximately corresponding to its period of operation – the building was undergoing gradual renovation and restoration work. The main structural elements of the Basilica building did not exhibit any damage traces indicating significantly exceeded Ultimate Limit State (SGN) and Serviceability Limit State (SLS) conditions.

Disturbing damage to the vault over the southern aisle was observed in autumn of 2018, at the end of October. Intense (in terms of number and opening width) scratches of the squinches and deformations (buckling relative to the vault plane) of the ribs were identified during a thorough inspection.

Vault ribs were cracked with a displacement and detached from the squinch surface, and the opening width reached 6–8 mm. Arch wall crack (crevice with a mutual edge shift) between the second and third pillar of the southern aisle, with a maximum opening width of 28 mm was identified. Fig. 3 shows damage concentration in the southern aisle pillar area and the cracks of wall elements.




Fig. 3. Simplified stock-taking of Basilica southern aisle damage [43]

3.2. Scope of soil seepage measurements

Extensive diagnostics [39–43], typical for historic buildings situated within a dense urban development, which covered the Basilica and its adjacent area, involved also detailed soil testing and the installation of piezometers for observing water levels in the subsoil. Locations of test boreholes and implemented piezometers are shown in Fig. 4.




Fig. 4. Location of subsoil test boreholes and groundwater level observation piezometers [40]

The piezometers were located around the temple with cyclical observations conducted. The measured water table levels are listed in Table 2.

The types of soil in the subsoil and their resistance to the action of seeping water were determined based on the conducted geotechnical studies. The piezometers measured water levels were used to develop a map of water level distribution within the Basilica subsoil and the seepage direction. Fig. 5 shows the groundwater table map for




Fig. 5. Groundwater table level map with marked soil profiles at the borehole and piezometer location, with seepage directions for 31/7/2019, against the background of the Basilica basement level plan

Table 2. List of groundwater table measurements using piezometers located around the Basilica building – values in m a.s.l.

Date	Observation well						
	P1	P2	P3	P4	P5	P6	P-R
02.07.2019	0.39	0.34	0.41	0.41	0.43	0.47	0.328
12.07.2019	0.49	0.60	0.36	0.46	0.04	0.56	0.328
20.07.2019	0.44	0.51	0.39	0.47	0.05	0.54	0.328
31.07.2019	0.41	0.38	0.33	0.43	0.03	0.49	0.328
01.10.2019	0.44	0.41	–	0.38	0.10	0.49	0.328
05.11.2019	0.57	0.45	–	0.37	0.22	0.55	0.328
19.11.2019	0.61	0.51	–	0.66	0.20	0.19	0.328
02.12.2019	0.59	0.50	–	0.52	0.19	2.93	0.328
03.02.2020	0.68	0.68	0.79	0.48	0.38	–	0.328
05.05.2020	0.94	0.86	0.84	0.98	0.60	0.99	0.328
08.05.2020	0.94	0.86	0.84	0.98	0.60	0.99	0.328
12.05.2020	0.94	0.91	0.89	0.98	0.6	1.34	–
13.05.2020	0.89	0.91	0.89	0.98	0.6	1.29	–
15.05.2020	0.94	0.86	0.89	0.98	0.6	1.14	–
18.05.2020	0.89	0.81	0.89	0.93	0.6	–	–
19.05.2020	0.89	0.81	0.79	0.98	0.6	–	–
20.05.2020	0.94	0.86	0.84	0.98	0.6	–	–
21.05.2020	0.94	0.86	0.89	0.98	0.5	–	–
22.05.2020	0.94	0.86	0.89	0.98	0.6	–	–
25.05.2020	0.94	0.86	0.84	0.98	0.6	–	–
26.05.2020	0.94	0.86	0.84	0.98	0.6	1.74	–
27.05.2020	0.94	0.86	0.84	0.98	0.6	1.74	–

31/7/2019, against the background of the Basilica basement level plan, with marked soil profiles in test boreholes and piezometers. Fig. 5 also shows water seepage directions resulting from piezometer groundwater levels. The analysis covered changing water levels on individual piezometers, as well as varying water seepage directions and seepage gradient values. Gradient values were analysed both along the entire length between the piezometers and locally, e.g., in the area of the pillars that experienced the greatest settlement.

Groundwater table level map for 2/12/2019 with seepage directions, against the background of the Basilica basement level plan is shown in Fig. 6.




Fig. 6. Groundwater table level map with seepage directions for 2/12/2019, against the background of the Basilica basement level plan

Fig. 7a shows the P5-P6 longitudinal profile and the position of the groundwater table curve position on 2/12/2019, and Fig. 7b shows the P2-P6 longitudinal profile and the position of the groundwater table curve position on 2/12/2019. Fig. 8 shows the P5-P2 longitudinal profile and the position of the groundwater table mean curve position and the local mean curve on 12/7/2019, as well as a diagram of pillar foundation level. Fig. 7–8 also show determined mean gradients between piezometers, relative to the critical gradients for




Fig. 7. Averaged groundwater table position within the Basilica area for 2/12/2019:
 a) P5-P6 longitudinal profile, b) P2-P6 longitudinal profile

given soil types. Red colour marks the soils with exceeded critical gradient values (Bligh criterion) [37].




Fig. 8. Averaged groundwater table position and local table change within the Basilica foundation area for 12/7/2019 – P5-P2 longitudinal profile

Determined mean gradient values along the entire section between all piezometers are listed in Table 3. Changing cell colour intensity marks the maximum (intensive red and blue) and minimum (white cells) gradient values for soils found in the Basilica subsoil.


Table 3. List of mean hydraulic gradient values between individual piezometers and piezometer no. 6 for selected measurement periods using piezometers located around the Basilica building

Obs. well no.	Direction	Slopes						
		02.07. 2019	31.07. 2019	01.10. 2019	19.11. 2019	02.12. 2019	05.05. 2020	26.05. 2020
P6	P1	0.14%	0.14%	0.09%	-0.72%	4.01%	0.09%	1.37%
	P2	0.41%	0.35%	0.25%	-1.01%	7.63%	0.41%	2.76%
	P3	0.20%	0.53%	l.d.	l.d.	l.d.	0.49%	2.96%
	P4	0.13%	0.13%	0.24%	-1.04%	5.36%	0.02%	1.69%
	P5	0.15%	1.68%	1.43%	-0.04%	10.04%	1.43%	4.18%
	P-R	0.28%	0.32%	0.32%	-0.28%	5.20%	1.32%	l.d.


Note: l.d. – lack of data

Fig. 9 and 10 show a groundwater table level map with seepage directions for several sample measurement days. The results depict how water levels and seepage directions in the Basilica subsoil change.

Subsequent Figs. 11 and 12 show a map of hydraulic gradients – declines in the groundwater table level with seepage directions, for several sample measurement days.



(a)



(b)

Fig. 9. Groundwater table level map with seepage directions for a) 12/7/2019 and b) 31/7/2019, against the background of the Basilica basement level plan






Fig. 10. Groundwater table level map with seepage directions for 3/2/2020, against the background of the Basilica basement level plan



(a)



(b)

Fig. 11. Map of local groundwater table declines with seepage directions for a) 12/7/2019 and b) 31/7/2020, against the background of the Basilica basement level plan




Fig. 12. Map of local groundwater table declines with seepage directions for 2/12/2019, against the background of the Basilica basement level plan

3.3. Analysis of soil seepage measurements

The presented results show how local declines in the Basilica area subsoil change. It can be clearly seen that the phenomenon varies over time, but qualitatively similar situations occur, such as on 2/12/2019 and 3/2/2020. The cyclical changes in the Basilica subsoil hydraulic gradients can initiate the formation of seepage-induced deformations. These changes can have various location, and the detachment of the subsoil from the Basilica floor was also found in several places.

The standard [44] describes the Ultimate Limit State (ULS) relative to the hydraulic uplifting of soil particles, internal erosion and hydraulic piping (HYD) in terms of failure caused by water flowing through a soil medium – understood as failure caused by the occurrence of run-off pressure, suffosion, silting-up, erosion or hydraulic piping. Evaluating the condition of historic buildings should take into account the possibility of this particular phenomenon occurring.

The results shown in Fig. 5–12 and Table 2 and 3. indicate that the subsoil under and around the Basilica building experiences the phenomenon of seepage-induced deformations induced by flowing groundwater. The extent of this phenomenon can be described as suffosion and characterized through a hydraulic gradient value or seepage rate leading to mechanical washing-out of fine soil particles by rainwater and groundwater, which seeps through the soil medium, ultimately leading to soil skeleton collapse and the formation of settlement.

The results of conducted measurements showed that the gradient values within the observation period ranged from 5.3% to 8.3%, and the mean hydraulic gradient for individual soil types found under the building was exceeded within the analysed sections (Fig. 7b). Locally, the closer to P6 the more the hydraulic gradient grows and exceeds critical values, with this gradient exceeded almost threefold in the immediate vicinity of P6 (Fig. 12). Exceeding the gradient for individual soil types can cause the suffosion phenomenon.

Obtained water flow direction visualisations (Fig. 9–12) indicate that the water flow direction in the Basilica building area also changes. Their intensity over such a small area is significant and unnatural. The magnitude of the flow direction changes themselves is important from the perspective of ongoing adverse seepage phenomena in the subsoil.

A detailed deformation analysis involving subsoil around the Basilica building enables formulating a thesis that the subsoil failure algorithm is significantly similar to the situation shown in [7]. The case described in [7] also involved periodic and intensive flows caused by the action of rainwater resulting in seepage-induced deformations and soil parameter changes.

3.4. Concepts of design solutions in terms of protecting the basilica building against soil seepage-induced deformations

In practice, the only effective method to protect a building against the development of seepage-induced deformations of the soil is to fully stabilize the water level within the subsoil. This situation is made possible through introducing drainage, most usually external and collection of rainwater to an efficient stormwater drainage system. Constant monitoring of the soil medium hydration level, including stormwater system tightness is also necessary.

It is only partially possible to limit soil seepage-induced deformations in the case of the Basilica building. There is a drainage system around the Basilica main body, which discharges water to a stormwater network through intermediate wells. However, as indicated by the pit excavated in the course of renovation work, the area around the building contains numerous non-inventoried drains, originating from different periods, executed at various foundation levels, some of which are patent and enable unobstructed water transport. Groundwater table fluctuations range from 14 (2/7/2019) up to even 274 cm (2/12/2019), which is confirmed by readings taken from the piezometers. The measurements conducted over time indicate that there is not direct correlation between executing construction work in the immediate and indirect vicinity of the Basilica building and the groundwater table level. The piezometer water level clearly rises in the case of intensive rainfall and in spring, i.e., in the period of elevated water level in the nearby Motława Canal. Rainwater flowing from the roof slope is discharged via a drain system to the rainwater drainage network, and the area around the main body of the Basilica is compacted and profiled with an incline towards “the outside” of the building.

4. Conclusions

Water level monitoring in the subsoil is very important for building safety, since it may indicate the formation of seepage-induced deformations.

Improper definition of the phenomena ongoing in the subsoil and incorrect application of seepage occurrence criteria may lead to design errors, especially in the case of work associated with reinforcing existing buildings, including historic religious structures.

The (Ultimate Limit State (ULS) in terms of HYD, which applies to failure caused by water flowing through a soil medium, should be obligatorily taken into account when evaluating the technical condition of historic buildings set within an area with groundwater flows.

In the case of the Basilica, cyclic changes of the hydraulic gradients in its subsoil could have initiated seepage-induced deformation in the past, which is reflected in the settling elements of a building like the Basilica, especially the floor in the area of the main body, as well as soil settlement under brick columns, which resulted in their settlement and failure of the ceramic vaults spread over them.

Water level changes in the vicinity should be limited to an absolute minimum or at least maximum values specified by critical gradients in order to protect Basilica structures. Water tables within its contour and inducing flow directly under the Basilica should be stabilized using newly designed drainages.

References

- [1] S. Bonelli, *Erosion of Geometarials*. London: Hoboken, NJ: ISTE, Wiley, 2012.
- [2] L. Ke and A. Takahashi, “Experimental investigations on suffusion characteristics and its mechanical consequences on saturated cohesionless soil”, *Soils and Foundations*, vol. 24, no. 4, pp. 713–730, 2014, doi: [10.1016/j.sandf.2014.06.024](https://doi.org/10.1016/j.sandf.2014.06.024).

- [3] T. C. Kenney and D. Lau, "Internal stability of granular filters", *Canadian Geotechnical Journal*, vol. 22, no. 2, pp. 215–225, 1985, doi: [10.1139/t85-029](https://doi.org/10.1139/t85-029).
- [4] H. Adamowicz and P. Popielski, "Analysis of changes in groundwater and soil conditions in a highly urbanized area due to deep building foundations", *Technical Transactions, Environmental Engineering*, vol. 2-Ś, pp. 3–20, 2015, doi: [10.4467/2353737XCT.15.222.4608](https://doi.org/10.4467/2353737XCT.15.222.4608).
- [5] K. Howard and R. Israfilov, *Current problems of hydrogeology in urban areas, urban agglomerates and industrial centers*. Kluwer Academic Publishers, 2002, doi: [10.1007/978-94-010-0409-1](https://doi.org/10.1007/978-94-010-0409-1).
- [6] J. Marsalek, B. E. Jimenez-Cisneros, P. A. Malmquist, M. Karamouz, J. Goldenfum, and B. Chocat, *Urban water cycle processes and interactions*. Unesco/IHP, 2006. [Online]. Available: https://www.ipcc.ch/apps/nj-lite/ar5wg2/nj-lite_download2.php?id=8016. [Accessed: 26 Oct. 2022].
- [7] J. Slusarek and M. Łupieżowicz, "Analysis of damage to structures as a result of soil suffusion", *Engineering Failure Analysis*, vol. 120, art. no. 105058, 2021, doi: [10.1016/j.engfailanal.2020.105058](https://doi.org/10.1016/j.engfailanal.2020.105058).
- [8] A. Halicka, "Ocena istniejących konstrukcji budowlanych według normy ISO 13822–2010 [Evaluation of existing construction structures as per standard ISO 13822–2010]", presented at 5th Polish National Conference – Technical and legal problems of building maintenance, 11-12.04.2019, Warszawa.
- [9] E. Kucharska-Stasiak, "Metody pomiaru zużycia obiektów budowlanych [Methods for measuring the building wear]", *Materiały Budowlane*, vol. 2, pp. 29–38, 1995 (in Polish).
- [10] W. Musiał and Z. Zwierzchowska, "Dokumentacja archiwalna jako podstawowe źródło informacji o obiekcie budowlanym [Archival documents as the basic source of information on a building]", presented at 7th Scientific and Technical Conference – Repair Issues in General Construction, 1996, Wrocław-Szklarska Poręba, Poland, 1996.
- [11] M. Substyk, *Utrzymanie i kontrola okresowa obiektów budowlanych*. Warsaw: ODDK, 2012.
- [12] G. Bartnik and M. Bukowski, "Analiza przyczyny spękań Kościoła parafialnego Św. Rocha w Jazgarzewie [The reasons of cracking of St. Roch Parish Church in Jazgarzew]", in *Proceedings of the 23rd Scientific and Technical Conference – Construction Failures – 2007, Szczecin-Międzyzdroje*. ZUT, 2007, pp. 207–212. [Online]. Available: <http://www.awarie.zut.edu.pl/files/ab2007/artykuly/0005.pdf>. [Accessed: 26 Oct. 2022].
- [13] T. Błaszczynski, H. Oleksiejuk, E. Firlei, and M. Błaszczynski, "Wielostopniowy monitoring i zabezpieczenie budynków pod ochroną konserwatorską przed awarią lub katastrofą [Multi-stage monitoring and protecting buildings under preservation maintenance against failure or disaster]", in *Proceedings of the 25th Scientific and Technical Conference – Construction Failures – 2011, Szczecin-Międzyzdroje*. ZUT, 2011, pp. 395–402.
- [14] Ł. Drobiec, "Przyczyny zniszczeń i sposób remontu murów Bazyliki Matki Boskiej Anielskiej w Dąbrowie Górniczej [Causes for destruction and repair method of the Our Lady of Angels Basilica in Dąbrowa Górnicza]", *Czasopismo Techniczne*, vol. 106, pp. 25–36, 2009 (in Polish).
- [15] Z. Janowski, "Problemy konstrukcyjne związane z odbudową Biblioteki Tynieckiej "Wielkiej Ruiny" w Opactwie Tynieckim [Structural issues associated with the reconstruction of the "Great Ruin" Tynec Library in the Tynec Abbey]", in *Proceedings of the 24th Scientific and Technical Conference – Construction Failures – 2009, Szczecin-Międzyzdroje*. ZUT, 2011, pp. 631–642.
- [16] Z. Janowski, Ł. Hojdys, and P. Krajewski, "Analiza oraz naprawa i rekonstrukcja sklepień w obiektach historycznych [Analysis, repair and reconstruction of vaults in historic buildings]", in *Proceedings of the 23rd Scientific and Technical Conference – Construction Failures – 2007, Szczecin-Międzyzdroje*. ZUT, 2007, pp. 251–260.
- [17] A. Malczyk, "Uszkodzenia i sposoby napraw konstrukcji murowej wież zabytkowej bazyliki [Failures and repair methods for the masonry structure in the towers of a historic basilica]", in *Proceedings of the 25th Scientific and Technical Conference – Construction Failures – 2011, Szczecin-Międzyzdroje*. ZUT, 2011, pp. 477–484.

- [18] L. Małyżko, R. Orłowicz, and A. Wasilewski, “Zastosowanie pomiarów fotograficzno-geodezyjnych do oceny wyciężenia mur [The application of photographic and geodetic measurements to evaluate wall effort]”, in *Proceedings of the 7th Scientific and Technical Conference – Repair Issues in General Construction, Wrocław-Szklarska Poręba*. 1996, pp. 105–114.
- [19] P. Matysek and M. Witkowski, “Badania wytrzymałości i odkształcalności XIX-wiecznych murów ceglanych [Strength and deformability testing of 19th century brick walls]”, in *Proceedings of the 26th Scientific and Technical Conference – Construction Failures – 2013, Szczecin-Międzyzdroje*. ZUT, 2007, pp. 183–190.
- [20] N. Stawiska and B. Stawiski, “Rewaloryzacja murów w obiektach zabytkowych [Restoration of walls in historic buildings]”, *Wiadomości Konserwatorskie*, vol. 11, pp. 18–22, 2005 (in Polish).
- [21] D. Wałach, J. Jaskowska-Lemańska, and P. Dybeł, “Analiza przyczyn powstania uszkodzeń kościoła pod wezwaniem Podwyższenia Krzyża Świętego w Podlegórzcu [Cause analysis of the damage to the Church of the Holy Cross Exaltation in Podlegórz]”, in *Proceedings of the 24th Scientific and Technical Conference – Construction Failures – 2009, Szczecin – Międzyzdroje*. ZUT, 2009, pp. 239–248.
- [22] E. Masłowski and D. Spizewska, *Wzmacnianie konstrukcji budowlanych [Reinforcing building structures]*. Warsaw: Arkady, 2000 (in Polish).
- [23] A. Mitzel, W. Stachurski, and J. Suwalski, *Awarie konstrukcji betonowych i murowych [Failures in concrete and masonry structures]*. Warsaw: Arkady, 1982 (in Polish).
- [24] P.G. Kossakowski, “Relocation of a Historic Building at the Old Norblin Factory in Warsaw”, *Archives of Civil Engineering*, vol. 67, no. 1, pp. 39–55, 2021, doi: [10.24425/ace.2021.136460](https://doi.org/10.24425/ace.2021.136460).
- [25] M. Kamiński, Ed., *Trwałość i skuteczność napraw obiektów budowlanych [Durability and effectiveness of building repairs]*. Wrocław: Dolnośląskie Wydawnictwo Edukacyjne, 2007 (in Polish).
- [26] S. Jurczakiewicz and S. Karczmarczyk, “Tension-Strut Systems in Conservation of Historical Buildings: Examples of Applications”, *Archives of Civil Engineering*, vol. 66, no. 3, pp. 659–674, 2020, doi: [10.24425/ace.2020.134419](https://doi.org/10.24425/ace.2020.134419).
- [27] International Commission on Large Dams, *International erosion of existing dams, levees and dikes, and their foundations. Bulletin 164. Vol. 1: Internal erosion processes and engineering assessment*. CIGB ICOLD, 2015. [Online]. Available: <http://www.ussdams.org/wp-content/uploads/2016/04/B164.pdf>. [Accessed: 26 Oct. 2022].
- [28] R. Moffat, R.J. Fannin, and S.J. Garner, “Spatial and temporal progression of internal erosion in cohesionless soil”, *Canadian Geotechnical Journal*, vol. 48, no. 3, pp. 399–412, 2011, doi: [10.1139/T10-071](https://doi.org/10.1139/T10-071).
- [29] J. Riha, Z. Alhasan, L. Petrula, P. Popielski, A. Dąbska, J.-J. Fry, S.V. Solski, N.A. Perevoshchikova, and F. Landstorfer, “Harmonisation of Terminology and Definitions on Soil Deformation Due to Seepage. In Internal Erosion in Earth-dams”, in *Internal Erosion in Earthdams, Dikes and Levees*, S. Bonelli, C. Jommi, D. Sterpi, Eds. Springer, 2018, pp. 347–366, doi: [10.1007/978-3-319-99423-9_31](https://doi.org/10.1007/978-3-319-99423-9_31).
- [30] A. Dąbska and P. Popielski, “Deformacje filtracyjne gruntów – klasyfikacja [Seepage deformation of soils – classification]”, *Gospodarka Wodna*, vol. 8, pp. 7–13, 2019 (in Polish).
- [31] K.S. Richards and K.R. Reddy, “Critical appraisal of piping phenomena in earth dams”, *Bulletin of Engineering Geology and the Environment*, vol. 66, no. 4, pp. 381–402, 2007, doi: [10.1007/s10064-007-0095-0](https://doi.org/10.1007/s10064-007-0095-0).
- [32] K.F. Busch, L. Luckner, and K. Tiemer, *Geohydraulik*, 3rd ed. Berlin, Germany: Gebrüder Borntraeger, 1993.
- [33] L. Ke and A. Takahashi, “Experimental investigations on suffusion characteristics and its mechanical consequences on saturated cohesionless soil”, *Soils and Foundations*, vol. 54, no. 4, pp. 713–730, 2014, doi: [10.1016/j.sandf.2014.06.024](https://doi.org/10.1016/j.sandf.2014.06.024).
- [34] L. Sibille, D. Marot, and Y. Sail, “A description of internal erosion by suffusion and induced settlements on cohesionless granular matter”, *Acta Geotechnica*, vol. 10, no. 6, pp. 735–748, 2015, doi: [10.1007/s11440-015-0388-6](https://doi.org/10.1007/s11440-015-0388-6).

- [35] O. Semar, K.J. Witt, and R.J. Fannin, "Suffusion evaluation – comparison of current approaches", in *Proceedings of the Fifth International Conference on Scour and Erosion*. American Society of Civil Engineering, 2010, pp. 251–261, doi: [10.1061/41147\(392\)24](https://doi.org/10.1061/41147(392)24).
- [36] Regulation of the Minister of Environment of 20 April 2007 on the technical conditions to be fulfilled by offshore hydrotechnical buildings and their locations. Dz.U.2007 nr 86 poz. 579. [Online]. Available: [https://isap.sejm.gov.pl/isap.nsf/DocDetails.xsp?id\\$=\\$WUDU20070860579](https://isap.sejm.gov.pl/isap.nsf/DocDetails.xsp?id$=$WUDU20070860579). [Accessed: 26 Oct. 2022].
- [37] W.G. Bligh, "Dams, barrages and weirs on porous foundations", *Engineering News Record*, vol. 64, no. 26, pp. 708–710, 1910.
- [38] I. Jantzer and S. Knutsson, "Critical gradients for tailing dam design", in *Proceedings of the First International Seminar on the Reduction of Risk in the Management of Tailing and Mine Waste, 29.08–01.10.2010, Perth, Australia*. E. Fourie, R. Jewell, Eds. Australian Centre for Geomechanics, 2010, pp. 23–32.
- [39] T. Majewski and M. Szczepkowski, "Program pomiarów poziomu wody gruntowej w piezometrach zamontowanych w sąsiedztwie budynku Bazyliki Św. Mikołaja w Gdańsku [Schedule of groundwater level measurements in piezometers installed in the vicinity of the St. Nicholas Basilica in Gdańsk]", Pracownia Projektowo-Inżynierska Tomasz Majewski, Gdynia, July 2019.
- [40] T. Majewski, M. Niedostatkiewicz, K. Wilde, M. Topolnicki, and P. Samul, "Opinia techniczna dotycząca oceny kierunku działań ratunkowych w Bazylice pw. Świętego Mikołaja zlokalizowanej w Gdańsku przy ulicy Świętojańskiej 72 w aspekcie zdarzenia losowego polegającego na uszkodzeniu sklepień południowej nawy bocznej [Technical evaluation of the direction of emergency activities in the St. Nicholas Basilica in Gdańsk, located at 72 Świętojańska Street, in respect of a random event involving damaged vaults of the southern aisle]", Politechnika Gdańska, Gdańsk, September 2019.
- [41] T. Majewski, M. Niedostatkiewicz, P. Samól, and M. Szczepkowski, "Program monitorowania dotyczący montażu i okresowej kontroli stanu szczelinomierzy w zabytkowym budynku Bazyliki pw. Św. Mikołaja w Gdańsku [A monitoring schedule concerning the installation and periodic inspection of gap gauge condition in the historic building of the St. Nicholas Basilica in Gdańsk]", Pracownia Projektowo-Inżynierska Tomasz Majewski, Gdynia, November 2019.
- [42] T. Majewski, L. Szerbiak, and K. Portasiak, "Program pomiarów geodezyjnych dotyczących przemieszczeń punktów pomiarowych zamontowanych na zabytkowych budynkach Klasztoru OO. Dominikanów w Gdańsku [A schedule of geodetic measurements concerning the displacement of measurement points installed on the historic buildings of the Dominican monastery buildings in Gdańsk]", Pracownia Projektowo-Inżynierska Tomasz Majewski, Gdynia, February 2020.
- [43] T. Majewski and M. Niedostatkiewicz, "Ekspertyza techniczna dotycząca uszkodzonych sklepień nawy południowej w budynku Bazyliki pw. Św. Mikołaja, zlokalizowanej w Gdańsku przy ul. Świętojańskiej 72 [Technical expert evaluation on damaged vaults of the southern aisle in the building of the St. Nicholas Basilica located in Gdańsk at 72 Świętojańska Street]", Pracownia Projektowo-Inżynierska Tomasz Majewski, Gdynia, October 2020.
- [44] EN 1997-1 Eurocode 7: Geotechnical design – Part 1. General rules. Poland, 1997.

Osiadanie zabytkowego budynku w wyniku deformacji filtracyjnych gruntu

Słowa kluczowe: Podłoże budowlane, filtracja w gruncie, osiadanie budynku, deformacje filtracyjne

Streszczenie:

W artykule dokonano przeglądu zagadnień związanych z wpływem przepływu wód gruntowych na właściwości i parametry gruntu, a tym samym na całą konstrukcję posadowionego na nim budynku. Filtracja wody przez grunt, podłoże budowlane lub elementy konstrukcyjne budowli

wykonanych z gruntu oddziałuje na szkielet gruntu i może prowadzić do zmian w układzie poszczególnych ziaren względem siebie, czyli do modyfikacji jego struktury. Odształcenia szkieletu gruntowego wynikające z działania sił filtracji nazywane są deformacjami filtracyjnymi. W artykule scharakteryzowano typowe deformacje wywołane filtracją wody w gruncie oraz podano kryterium określające moment pojawiania się danego zjawiska. W studium przypadku wykorzystano dane dotyczące spękań i odształceń w zabytkowym budynku oraz filtracji wody w jego podłożu. Na podstawie danych z monitoringu poziomu wody gruntowej przeanalizowano przepływ wód podziemnych i wyznaczono strefy, w których przekroczone zostało kryterium inicjacji procesu sufozji. Wyznaczone strefy pokrywają się z lokalizacją pęknięć i zarysowań budynku i potwierdzają możliwą przyczynę jego uszkodzenia.

2022-07-09, Revised: 2022-12-13

CONTENTS – SPIS TREŚCI

Pawel Popielski, Bartosz Bednarz, Tomasz Majewski, Maciej Niedostatkiwicz
Settlement of a historic building due to seepage-induced soil deformation 65